

End-of-Sale and End-of-Life Announcement for the Select CiscoView Device Managers 1.0 and 1.1

EOL5844

Cisco Systems® announces the end-of-sale and end-of life dates for the Select CiscoView Device Managers 1.0 and 1.1. This end-of-sale and end-of life affects CiscoView Device Manager products for the following devices, see details in table 2:

- Cisco Catalyst 6500 Series Switch
- Cisco Catalyst 6500 Series SSL Services Module
- Cisco Catalyst 6500 Series WebVPN Services Module
- Cisco Catalyst 6500 Series IPSec VPN Services Module

The following CiscoView Device Manager products for the following devices are not discontinued and remain available:

- Cisco Content Switching Module
- Cisco Content Service Switch

The last day to order the Select CiscoView Device Managers 1.0 and 1.1 is June 20, 2007. Customers with active service contracts will continue to receive support from the Cisco Technical Assistance Center (TAC) as shown in Table 1 of the EoL bulletin. Table 1 describes the end-of-life milestones, definitions, and dates for the Select CiscoView Device Managers 1.0 and 1.1. Table 2 lists the product part numbers affected by this announcement.

Table 1. End-of-Life Milestones and Dates for the Select CiscoView Device Managers 1.0 and 1.1

Milestone	Definition	Date
End-of-Sale Date	The last date to order the product through Cisco point-of-sale mechanisms. The product is no longer for sale after this date.	June 20, 2007
End of SW Maintenance Releases Date: App. SW	The last date that Cisco Engineering may release any final software maintenance releases or bug fixes. After this date, Cisco Engineering will no longer develop, repair, maintain, or test the product software.	June 20, 2007
End of Service Contract Renewal Date: App. SW	The last date to extend or renew a service contract for the product.	June 20, 2007
Last Date of Support: App. SW	The last date to receive service and support for the product. After this date, all support services for the product are unavailable, and the product becomes obsolete.	December 20, 2007

HW = Hardware

OS SW = Operating System Software

App. SW = Application Software

Table 2. Product Part Numbers Affected by This Announcement

End-of-Sale Product Part Number	Product Description
CVDM-C6500-1.0	CiscoView Device Mgr 1.0 for Catalyst 6500 Series
CVDM-C6500-1.0-K9	CiscoView Device Mgr 1.0 for Catalyst 6500 Series 3DES
CVDM-C6500-1.1	CiscoView Device Mgr 1.1 for Catalyst 6500 Series
CVDM-C6500-1.1-K9	CiscoView Device Mgr 1.1 for Catalyst 6500 Series 3DES
CVDM-SSLSM-1.0-K9	CiscoView Device Mgr 1.0 for SSL Services Mod 3DES
CVDM-SSLSM-1.1-K9	CiscoView Device Mgr 1.1 for SSL Services Mod 3DES
CVDM-VPNSM-1.1-K9	CiscoView Device Mgr 1.1 for VPN Services Mod 3DES
CVDM-WEBVPN-1.1-K9	CiscoView Device Mgr 1.1 for WebVPN Services Mod 3DES

Product Migration Options

It is advised to contact Cisco sales channels to obtain information on replacement products.

Customers can use the Cisco Technology Migration Plan (TMP) to trade in products and receive credit toward the purchase of new Cisco equipment. For more information about Cisco TMP, go to <http://www.cisco.com/go/tradein/>. The Cisco TMP application requires all users to have a Cisco.com user ID.

Customers may be able to continue to purchase the end-of-sale product through Cisco's Authorized Refurbished Equipment program. Refurbished units of the end-of-sale product are available in limited supply for sale in certain countries on a first-come, first-served basis. For information about the refurbished equipment program, go to http://www.cisco.com/en/US/ordering/or6/or17/order_refurbished_equipment_program_description.html.

For More Information

For more information about the replacement products, consult Cisco Sales or Technical Assistance Center.

For more information about the Cisco End-of-Life Policy, go to http://www.cisco.com/en/US/products/prod_end_of_life.html.

To subscribe to receive end-of-life/end-of-sale information, go to <http://www.cisco.com/cgi-bin/Support/FieldNoticeTool/field-notice>.



Americas Headquarters
 Cisco Systems, Inc.
 170 West Tasman Drive
 San Jose, CA 95134-1706
 USA
www.cisco.com
 Tel: 408 526-4000
 800 553-NETS (6367)
 Fax: 408 527-0689

Asia Pacific Headquarters
 Cisco Systems, Inc.
 16B Robinson Road
 #29-01 Capital Tower
 Singapore 068912
www.cisco.com
 Tel: +85 6317 7777
 Fax: +85 6317 7769

Europe Headquarters
 Cisco Systems International BV
 Hoenderbergpark
 Hoenderbergweg 13-19
 1101 CH Amsterdam
 The Netherlands
www-europe.cisco.com
 Tel: +31 0 20 620 6791
 Fax: +31 0 20 557 1100

Cisco has more than 200 offices worldwide. Addresses, phone numbers, and fax numbers are listed on the Cisco Website at www.cisco.com/go/offices.

©2007 Cisco Systems, Inc. All rights reserved. CCVP, the Cisco logo, and the Green Route Bridge logo are trademarks of Cisco Systems, Inc. Changing the Way We Work, Live, Play and Learn is a service mark of Cisco Systems, Inc.; and Access, Registrar, Aironet, BPX, Catalyst, CCMA, CCDP, CCEM, CCI, CCNA, CCNP, CCSP, Cisco, the Cisco Certified Internetwork Expert logo, Cisco IOS, Cisco Press, Cisco Systems, Cisco Systems Capital, the Cisco Systems logo, Cisco Unity, Enterprise/Solved, EtherChannel, EtherFast, EtherSwitch, Fast Step, Follow Me Browsing, FormShare, GigaDrive, HomeLink, Internet Quotient, IOS, IPPhone, IPTV, IQ Expertise, the IQ logo, IQ Net, RealTime Scorecard, iQuick Study, Lightspeed, Linksys, MeetingPlace, MGX, Networking Academy, Network Registrar, Packet, PIX, ProConnect, ServiceShare, SMARTnet, StackWise, The Fastest Way to Increase Your Internet Quotient, and TransPath are registered trademarks of Cisco Systems, Inc. and/or its affiliates in the United States and certain other countries.

All other trademarks mentioned in this document or Website are the property of their respective owners. The use of the word partner does not imply a partnership relationship between Cisco and any other company. (070509)