

## End-of-Sale and End-of-Life Announcement for the Cisco 12000 Series 4-Slot and 6-Slot Legacy Fabric

EOL6360

Cisco® announces the end-of-sale and end-of life dates for the Cisco 12000 Series 4-Slot and 6-Slot Legacy Fabric. The last day to order the affected product(s) is May 15, 2009. Customers with active service contracts will continue to receive support from the Cisco Technical Assistance Center (TAC) as shown in Table 1 of the EoL bulletin. Table 1 describes the end-of-life milestones, definitions, and dates for the affected product(s). Table 2 lists the product part numbers affected by this announcement. For customers with active and paid service and support contracts, support will be available until the termination date of the contract, even if this date exceeds the Last Date of Support shown in Table 1.

**Table 1.** End-of-Life Milestones and Dates for the Cisco 12000 Series 4-Slot and 6-Slot Legacy Fabric

Milestone	Definition	Date
<b>End-of-Life Announcement Date</b>	The date the document that announces the end of sale and end of life of a product is distributed to the general public.	May 15, 2008
<b>End-of-Sale Date</b>	The last date to order the product through Cisco point-of-sale mechanisms. The product is no longer for sale after this date.	May 15, 2009
<b>Last Ship Date: HW</b>	The last-possible ship date that can be requested of Cisco and/or its contract manufacturers. Actual ship date is dependent on lead time.	August 14, 2009
<b>End of SW Maintenance Releases Date OS SW</b>	The last day that Cisco Engineering may release any final software maintenance releases or bug fixes. After this date, Cisco Engineering will no longer develop, repair, maintain, or test the product software.	May 15, 2012
<b>End of Routine Failure Analysis Date: HW</b>	The last-possible date a routine failure analysis may be performed to determine the cause of product failure or defect.	May 15, 2010
<b>End of New Service Attachment Date: HW</b>	For equipment and software that is not covered by a service-and-support contract, this is the last date to order a new service-and-support contract or add the equipment and/or software to an existing service-and-support contract.	May 15, 2010
<b>End of Service Contract Renewal Date: HW</b>	The last date to extend or renew a service contract for the product.	August 13, 2013
<b>Last Date of Support: HW</b>	The last date to receive service and support for the product. After this date, all support services for the product are unavailable, and the product becomes obsolete.	May 14, 2014

HW = Hardware      OS SW = Operating System Software      App. SW = Application Software

**Table 2.** Product Part Numbers Affected by This Announcement

End-of-Sale Product Part Number	Product Description	Replacement Product Part Number	Replacement Product Description
<b>12006-CSC</b>	12006 Advanced Clock Scheduler Card	12006E-CSC	12006 30Gbps Enhanced Clock Scheduler
<b>12006-CSC=</b>	12006 Advanced Clock Scheduler Card	12006E-CSC=	30Gbps Enhanced Clock Scheduler Card for 12006 Chassis
<b>12006-SFC</b>	12006 Advanced Switch Fabric Card	12006E-SFC	30Gbps Enhanced Switch Fabric Card for 12006 Chassis

<b>12006-SFC=</b>	12006 Advanced Switch Fabric Card	12006E-SFC=	Enhanced Switch Fabric Card for Cisco 12006
<b>12006/30</b>	30Gbps Fabric Option with 3xSFC and 2xCSC for 12006 Chassis	12006E/30	30Gbps Enhanced Fabric with 3SFC and 2CSC for Cisco 12006
<b>12404/80</b>	80Gbps consolidated Fabric and Alarm card for 12404 chassis	12404E/80	80Gbps Enhanced Consolidated Fabric and Alarm for Cisco12404
<b>12404/80=</b>	80Gbps consolidated Fabric and Alarm card for 12404 chassis	12404E/80=	80Gbps Enhanced Consolidated Fabric and Alarm for Cisco12404
<b>12406/120</b>	120Gbps Fabric Option with 3xSFC and 2xCSC for 12406 chassis	12406E/120	120Gbps Enhanced Fabric with 3xSFC and 2xCSC for Cisco 12406
<b>12406/120=</b>	120Gbps Fabric Kit with 3xSFC and 2xCSC for 12406 chassis	12406E/120=	120Gbps Enhanced Fabric with 3xSFC and 2xCSC for Cisco 12406
<b>GSR04-FABRIC</b>	Cisco 12404 Consolidated Fabric/Alarm	12404E/80	80Gbps Enhanced Consolidated Fabric and Alarm for Cisco12404
<b>GSR04-FABRIC=</b>	GSR 12404 Consolidated Fabric/Alarm	12404E/80=	80Gbps Enhanced Consolidated Fabric and Alarm for Cisco12404
<b>GSR6-CSC</b>	Cisco 12406 Clock Scheduler Card	12006E-CSC	12006 30Gbps Enhanced Clock Scheduler
<b>GSR6-CSC/R</b>	Redundant CSC for GSR6/120	12006E-CSC	12006 30Gbps Enhanced Clock Scheduler
<b>GSR6-CSC=</b>	Spare Clock Scheduler	12006E-CSC=	30Gbps Enhanced Clock Scheduler Card for 12006 Chassis
<b>GSR6-SFC</b>	Cisco 12406 Switch Fabric Card	12006E-SFC	30Gbps Enhanced Switch Fabric Card for 12006 Chassis
<b>GSR6-SFC=</b>	Spare Switch Fabric	12006E-SFC=	Enhanced Switch Fabric Card for Cisco 12006

### Product Migration Options

Customers are encouraged to migrate to the Cisco 12000 Series 4-Slot and 6-Slot Enhanced Fabric. Information about this product can be found at:

[http://www.cisco.com/en/US/prod/collateral/routers/ps6342/product\\_data\\_sheet0900aecd80303d86\\_ps167\\_Products\\_Data\\_Sheet.html](http://www.cisco.com/en/US/prod/collateral/routers/ps6342/product_data_sheet0900aecd80303d86_ps167_Products_Data_Sheet.html).

Customers can use the Cisco Technology Migration Plan (TMP) to trade in products and receive credit toward the purchase of new Cisco equipment. For more information about Cisco TMP, go to: <http://www.cisco.com/go/tradein/>. The Cisco TMP application requires all users to have a Cisco.com user ID.

Customers may be able to continue to purchase the Cisco 12000 Series 4-Slot and 6-Slot Legacy Fabric through the Cisco Certified Refurbished Equipment program. Refurbished units may be available in limited supply for sale in certain countries on a first-come, first-served basis until the Last Date of Support has been reached. For information about the Cisco Certified Refurbished Equipment program, go to: <http://www.cisco.com/go/eos>.

## For More Information

For more information about the Cisco 12000 Series 4-Slot and 6-Slot Enhanced Fabric, visit [http://www.cisco.com/en/US/prod/collateral/routers/ps6342/product\\_data\\_sheet0900aecd80303d86\\_ps167\\_Products\\_Data\\_Sheet.html](http://www.cisco.com/en/US/prod/collateral/routers/ps6342/product_data_sheet0900aecd80303d86_ps167_Products_Data_Sheet.html), or contact your local account representative.

To request information about the Cisco 12000 Series 4-Slot and 6-Slot Enhanced Fabric, send an e-mail to [ask-gsr-pm@cisco.com](mailto:ask-gsr-pm@cisco.com).

For more information about the Cisco End-of-Life Policy, go to: [http://www.cisco.com/en/US/products/prod\\_end\\_of\\_life.html](http://www.cisco.com/en/US/products/prod_end_of_life.html).

To subscribe to receive end-of-life/end-of-sale information, go to: <http://www.cisco.com/cgi-bin/Support/FieldNoticeTool/field-notice>.



**Americas Headquarters**  
Cisco Systems, Inc.  
San Jose, CA

**Asia Pacific Headquarters**  
Cisco Systems (USA) Pte. Ltd.  
Singapore

**Europe Headquarters**  
Cisco Systems International BV  
Amsterdam, The Netherlands

Cisco has more than 200 offices worldwide. Addresses, phone numbers, and fax numbers are listed on the Cisco Website at [www.cisco.com/go/offices](http://www.cisco.com/go/offices).

CCDE, CCENT, Cisco Eos, Cisco Lumin, Cisco StadiumVision, the Cisco logo, DCE, and Welcome to the Human Network are trademarks; Changing the Way We Work, Live, Play, and Learn is a service mark; and Access Registrar, Aironet, AsyncOS, Bringing the Meeting To You, Catalyst, CCDA, CCDP, CCIE, CCIP, CCNA, CCNP, CCSP, CCVP, Cisco, the Cisco Certified Internetwork Expert logo, Cisco IOS, Cisco Press, Cisco Systems, Cisco Systems Capital, the Cisco Systems logo, Cisco Unity, Collaboration Without Limitation, EtherFast, EtherSwitch, Event Center, Fast Step, Follow Me Browsing, FormShare, GigaDrive, HomeLink, Internet Quotient, IOS, iPhone, iQ Expertise, the iQ logo, iQ Net Readiness Scorecard, iQuick Study, IronPort, the IronPort logo, LightStream, Linksys, MediaTone, MeetingPlace, MGX, Networkers, Networking Academy, Network Registrar, PCNow, PIX, PowerPanels, ProConnect, ScriptShare, SenderBase, SMARtNet, Spectrum Expert, StackWise, The Fastest Way to Increase Your Internet Quotient, TransPath, WebEx, and the WebEx logo are registered trademarks of Cisco Systems, Inc. and/or its affiliates in the United States and certain other countries.

All other trademarks mentioned in this document or Website are the property of their respective owners. The use of the word partner does not imply a partnership relationship between Cisco and any other company. (0804R)