



End-of-Sale and End-of-Life Announcement for the Cisco PGW 2200 Softswitch 9.6(1)

EOL6425

Cisco® announces the end-of-sale and end-of life dates for the Cisco PGW 2200 Softswitch 9.6(1). The last day to order the affected product(s) is October 29, 2008. Customers with active service contracts will continue to receive support from the Cisco Technical Assistance Center (TAC) as shown in Table 1 of the EoL bulletin. Table 1 describes the end-of-life milestones, definitions, and dates for the affected product(s). Table 2 lists the product part numbers affected by this announcement. For customers with active and paid service and support contracts, support will be available until the termination date of the contract, even if this date exceeds the Last Date of Support shown in Table 1.

Table 1. End-of-Life Milestones and Dates for the Cisco PGW 2200 Softswitch 9.6(1)

Milestone	Definition	Date
End-of-Life Announcement Date	The date the document that announces the end of sale and end of life of a product is distributed to the general public.	April 30, 2008
End-of-Sale Date	The last date to order the product through Cisco point-of-sale mechanisms. The product is no longer for sale after this date.	October 29, 2008
Last Ship Date: App. SW	The last-possible ship date that can be requested of Cisco and/or its contract manufacturers. Actual ship date is dependent on lead time.	January 27, 2009
End of SW Maintenance Releases Date: App. SW	The last date that Cisco Engineering may release any final software maintenance releases or bug fixes. After this date, Cisco Engineering will no longer develop, repair, maintain, or test the product software.	October 29, 2009
End of New Service Attachment Date: App. SW	For equipment and software that is not covered by a service-and-support contract, this is the last date to order a new service-and-support contract or add the equipment and/or software to an existing service-and-support contract.	October 29, 2009
End of Service Contract Renewal Date: App. SW	The last date to extend or renew a service contract for the product.	January 25, 2011
Last Date of Support: App. SW	The last date to receive service and support for the product. After this date, all support services for the product are unavailable, and the product becomes obsolete.	October 29, 2011

HW = Hardware OS SW = Operating System Software App. SW = Application Software

Table 2. Product Part Numbers Affected by This Announcement

End-of-Sale Product Part Number	Product Description	Replacement Product Part Number	Replacement Product Description
BAMS	Billing And Measurements Software	PGW2200-BAMS	PGW2200 BAMS System
HSI	H.323 Signaling Interface	PGW2200-HSI	PGW2200 H.323 System
PGW2200-FF	PGW 2200 Fully Featured SoftSwitch System	PGW2200-FFX	Fully Featured PGW 2200 Softswitch System
PGW2200-FF-SW-ONLY	PGW 2200 Fully Featured SoftSwitch System SW Only	PGW2200-FFX	Fully Featured PGW 2200 Softswitch System
SFB22-CC-9.6.1	PGW 2200 Application SW v9.6.1 on CD	SFB22-CC-9.7.3	PGW 2200 Application Software Ver 9.7(3) on CD

SFB22-DPNSS	PGW 2200 DPNSS Right-to-Use Lic (Call Control) - 10 E1s/T1s	SFB22-PBX	PGW 2200 PBX Interface (DPNSS/QSIG) Right-to-Use License
SFB22-INAP	PGW 2200 INAP Interface Right-to-Use License	SFB22-INAPX	PGW 2200 INAP Interface Right-to-Use License
SFB22-MP-9.6.1	MicroPOP App SW for PGW-S v9.6.1 (min qty 5)	There is currently no replacement product available for this product.	
SFB22-PBXRTU-120=	PGW 2200 PBX RTU Lic (Call Cont) - 10 E1/T1 (120-Up RTUs)	There is currently no replacement product available for this product.	
SFB22-PBXRTU-30=	PGW 2200 PBX RTU Lic (Call Cont) - 10 E1/T1 (30-59 RTUs)	There is currently no replacement product available for this product.	
SFB22-PBXRTU-60=	PGW 2200 PBX RTU Lic (Call Cont) - 10 E1/T1 (60-119 RTUs)	There is currently no replacement product available for this product.	
SFB22-QSIG	PGW 2200 Q.SIG Right-to-Use Lic (Call Control) - 10 E1s/T1s	SFB22-PBX	PGW 2200 PBX Interface (DPNSS/QSIG) Right-to-Use License
SFB22-SIP	PGW2200 SIP RTU License for 2000 Call Legs (CC Mode)	SWP22-SIP-RTU	PGW 2200 SIP Per Call leg Run Time License, 2k Call Legs
SFB22-SIP=	PGW SIP interface spare	SWP22-SIP-RTU	PGW 2200 SIP Per Call leg Run Time License, 2k Call Legs
SFB22-SWO-CC-9.6.1	Fully Featured PGW 2200 Base Application Software Ver 9.6(1)	SFB22-CC-9.7.3	PGW 2200 Application Software Ver 9.7(3) on CD
SFB22-SWO-MP-9.6.1	Micro POP PGW 2200 Base Application Software Ver 9.6(1)	There is currently no replacement product available for this product.	
SFB22-SWO-VM-9.6.1	PGW-S Base Application SW for Voice Mail Apps V9.6.1	There is currently no replacement product available for this product.	
SFB22-VM-9.6.1	Voice Mail GW App SW For PGW-S v9.6.1	There is currently no replacement product available for this product.	
SFBBA-3.20	BAMS Application SW v3.20	SFBBA-3.3	BAMS Application SW V 3.30 on CD
SFBBA-SWO-3.20	BAMS Application SW v3.20 for SW Only Systems	SFBBA-3.3	BAMS Application SW V 3.30 on CD
SFBHSI-4.2	HSI App SW Ver 4.2 for 2000 Call Legs Only (CC Mode)	SFBHSI-4.3	HSI Application Software V 4.3 supporting PGW 9.7
SFBHSI-4.2	HSI App SW Ver 4.2 for 2000 Call Legs Only (CC Mode)	SWP22-H323-RTU	PGW 2200 H.323 Per Call leg Run Time License, 2k Call Legs
SFBHSI-SWO-4.2	HSI App SW Ver 4.2 for 2000 Call Legs Only (CC Mode)	SFBHSI-4.3	HSI Application Software V 4.3 supporting PGW 9.7
SFBHSI-SWO-4.2	HSI App SW Ver 4.2 for 2000 Call Legs Only (CC Mode)	SWP22-H323-RTU	PGW 2200 H.323 Per Call leg Run Time License, 2k Call Legs
SWP22-CC-100K-RTU	PGW 2200 Call Control License for 1k Ports, Ports >=100k	There is currently no replacement product available for this product.	
SWP22-CC-50K-RTU	PGW 2200 Call Control License for 1k Ports, Ports >=50k	There is currently no replacement product available for this product.	
SWP22-CC-75K-RTU	PGW 2200 Call Control License for 1k Ports, Ports >=75k	There is currently no replacement product available for this product.	
SWP22-CC-RTU	PGW 2200 (Call Control) Voice or Dial RTU License, 1k Ports	SWP22-CCX-RTU	PGW 2200 (Call Control) Voice or Dial RTU License, 1k Ports

SWP22-CC-RTU=	PGW CC RTU Spare	SWP22-CCX-RTU	PGW 2200 (Call Control) Voice or Dial RTU License, 1k Ports
SWP22-DPNSS-RTU	PGW 2200 DPNSS Right-to-Use Lic (Call Control) - 10 E1s/T1s	There is currently no replacement product available for this product.	
SWP22-MP-TO-FF	PGW 2200 Upgrade to Fully Featured from Micro POP	There is currently no replacement product available for this product.	
SWP22-QSIG-RTU	PGW 2200 Q.SIG Right-to-Use Lic (Call Control) - 10 E1s/T1s	There is currently no replacement product available for this product.	
SWP22-S-RTU	PGW 2200 (Signaling) Voice or Dial RTU License, 1k Ports	SWP22-SX-RTU	PGW 2200 (Signaling) Voice or Dial RTU License, 1k Ports
SWP22-VM-RTU-120	VMGW RTU 120 ports	There is currently no replacement product available for this product.	
SWP22-VM-RTU-1K	VMGW RTU 1000 ports	There is currently no replacement product available for this product.	
SWP22-VM-RTU-240	VMGW RTU 240 ports	There is currently no replacement product available for this product.	
SWP22-VM-RTU-480	VMGW RTU 480 ports	There is currently no replacement product available for this product.	
SWP22-VM-RTU-60	VMGW RTU 60 ports	There is currently no replacement product available for this product.	
UP22-9X-RTU	PGW SW Upgrade to Ver 9.x (Voice/Dial) 1k Ports	There is currently no replacement product available for this product.	
UP22-CC-9.6.1	Upgrade to PGW 2200 App SW v9.6.1	There is currently no replacement product available for this product.	
UP22-CC-9.6.1=	Upgrade to PGW 2200 App SW v9.6.1 Spare	There is currently no replacement product available for this product.	
UP22-MP-9.6.1	Upgrade To MicroPOP App SW for PGW-S v9.6.1 (min qty 5)	There is currently no replacement product available for this product.	
UP22-MP-9.6.1=	Upgrade To MicroPOP App SW for PGW-S v9.6.1 (min 5) Spare	There is currently no replacement product available for this product.	
UP22-VM-9.6.1	Upgrade To Voice Mail GW App SW For PGW-S v9.6.1	There is currently no replacement product available for this product.	
UP22-VM-9.6.1=	Upgrade To Voice Mail GW App SW For PGW-S v9.6.1 Spare	There is currently no replacement product available for this product.	
UP22BAMS-3.20	Upgrade To BAMS App SW v3.20	There is currently no replacement product available for this product.	
UP22BAMS-3.20=	Upgrade To BAMS App SW v3.20 Spare	There is currently no replacement product available for this product.	
UP22HSI-4.2	Upgrade To HSI App SW v4.2	There is currently no replacement product available for this product.	
UP22HSI-4.2=	Upgrade To HSI App SW v4.2 Spare	There is currently no replacement product available for this product.	

Product Migration Options

Customers are encouraged to migrate to the Cisco PGW 2200 Softswitch 9.7(3) and its supporting products. Information about this product can be found at:

<http://www.cisco.com/en/US/products/hw/vcallcon/ps2027/index.html>.

For More Information

For more information about the Cisco PGW 2200 Softswitch 9.7(3), visit <http://www.cisco.com/en/US/products/hw/vcallcon/ps2027/index.html>, or contact your local account representative.

For more information about the Cisco End-of-Life Policy, go to:

http://www.cisco.com/en/US/products/prod_end_of_life.html.

To subscribe to receive end-of-life/end-of-sale information, go to:

<http://www.cisco.com/cgi-bin/Support/FieldNoticeTool/field-notice>.



Americas Headquarters
Cisco Systems, Inc.
San Jose, CA

Asia Pacific Headquarters
Cisco Systems (USA) Pte. Ltd.
Singapore

Europe Headquarters
Cisco Systems International BV
Amsterdam, The Netherlands

Cisco has more than 200 offices worldwide. Addresses, phone numbers, and fax numbers are listed on the Cisco Website at www.cisco.com/go/offices.

CCDE, CCENT, Cisco Eos, Cisco Lumin, Cisco StadiumVision, the Cisco logo, DCE, and Welcome to the Human Network are trademarks; Changing the Way We Work, Live, Play, and Learn is a service mark; and Access Registrar, Aironet, AsyncOS, Bringing the Meeting To You, Catalyst, CCDA, CCDP, CCIE, CCIIP, CCNA, CCNP, CCSP, CCVP, Cisco, the Cisco Certified Internetwork Expert logo, Cisco IOS, Cisco Press, Cisco Systems, Cisco Systems Capital, the Cisco Systems logo, Cisco Unity, Collaboration Without Limitation, EtherFast, EtherSwitch, Event Center, Fast Step, Follow Me Browsing, FormShare, GigaDrive, HomeLink, Internet Quotient, IOS, iPhone, iQ Expertise, the iQ logo, iQ Net Readiness Scorecard, iQuick Study, IronPort, the IronPort logo, LightStream, Linksys, MediaTone, MeetingPlace, MGX, Networkers, Networking Academy, Network Registrar, PCNow, PIX, PowerPanels, ProConnect, ScriptShare, SenderBase, SMARtNet, Spectrum Expert, StackWise, The Fastest Way to Increase Your Internet Quotient, TransPath, WebEx, and the WebEx logo are registered trademarks of Cisco Systems, Inc. and/or its affiliates in the United States and certain other countries.

All other trademarks mentioned in this document or Website are the property of their respective owners. The use of the word partner does not imply a partnership relationship between Cisco and any other company. (0804R)